

The Safety Tool Specialists

Insulated 1000V Rated Hand Tools Insulating Rubber Goods Arc Flash PPE

MER BROMS IMPOLICIE

BEFORE USERAG



Cementex Products Inc. 650 Jacksonville Rd. • P.O. Box 1533 Burlington, NJ 08016

www.cementexusa.com orders@cementexusa.com • rfq@cementexusa.com

REAKTY'S FROM SERVIC

609.387.1040 • 800.654.1292 fax: 609.386.8885



ELECTRICAL SAFETY COMPLIANCE CHART FOR NFPA 70E AND CSA Z462

Energized work shall only be performed when permitted by 70E 130.2(A) / Z462 4.3.2.2. For tasks not listed or for power systems with greater than the assumed maximur short circuit current capacity or with longer than the assumed maximum fault clearing times, an arc flash hazard analysis shall be required in accordance with 70E 130.5 / Z462 4.3.5. This summary table is only for use by QUALIFIED PERSONNEL that have been trained in accordance with the most current version of NFPA 70E Articles 110, 120 and 130 / CSA Z462 Clause 4.

Tasks Performed on Energized Equipment (600 volts or less): 70E 130.7(C)(15)(a) / Z462 Table 4A

Table A Panelboards or Other Equipment Rated 240 V and Below Note 1		-
Perform infrared thermography and other non-contact inspections outside the	LWG	0
restricted approach boundary	10000	
Circuit breaker (CB) or fused switch operation with covers on	LWG	0
CB or fused switch operation with covers off	LWG	0
Work on energized electrical conductors and circuit parts, including voltage testing	IG/IT	1
Remove / Install CBs or fused switches	IG/IT	1
Removal of bolted covers (to expose bare, energized electrical		
conductors and circuit parts)	LWG	1
Opening hinged covers (to expose bare, energized electrical conductors		
and circuit parts)	LWG	0
Work on energized electrical conductors and circuit parts of utilization	10/17	
equipment fed directly by a branch circuit of the panelboard	IG/IT	1
Table B Panelboards or Switchboards Rated >240 V and up to 600 V		
(with molded case or insulated case circuit breakers) Note 1		
Perform infrared thermography and other non-contact inspections outside	LWG	1
CB or fused switch operation with enclosure doors closed	LWG	0
CB or fused switch operation with covers off	IG	1
Work on energized electrical conductors and circuit parts, including voltage testing	IG/IT	2
Remove/install CBs or fused switches	IG/IT	2
Removal of bolted covers (to expose bare, energized electrical conductors and		
circuit parts)	LWG	1
Opening hinged covers (to expose bare, energized electrical conductors and circuit	LWG	0
Work on energized electrical conductors and circuit parts of utilization equipment	TOUT	2
fed directly by a branch circuit of the panelboard or switchboard	IG/IT	2
Table C Other 600 V Class (277 V through 600 V nominal) Equipment		
Note 2 (except as indicated)		
Lighting or small power transformers (600 V maximum)		
Removal of bolted covers	LWG	2
(to expose bare, energized electrical conductors and circuit parts)	LWG	2
Opening hinged covers	114/0	
(to expose bare, energized electrical conductors and circuit parts)	LWG	1
Application of safety grounds, after voltage test	IG	2
Work on energized electrical conductors and circuit parts, including voltage		
testing	IG/IT	2
Revenue meters (kW-hour, at primary voltage and current) Insertion or removal	IG	2
Cable trough or tray cover removal or installation	LWG	1
Miscellaneous equipment cover removal or installation	LWG	1
Work on energized electrical conductors and circuit parts, including		
voltage testing	IG/IT	2
Application of safety grounds, after voltage test	IG	2
Insertion or removal of plug-in devices into or from busways	IG	2

CLOTHING AND/OR EQUIPMENT	HRC	HRC	HRC	HRC	HRC
70E 130.7 (C)(16) / Z462 Table 5	0	1	2	3	4
Arc Thermal Protective Value in Cal/Cm ² (minimum)	0	4	8	25	40
Non-melting/untreated natural fiber long-sleeve shirt	Х				
Non-melting/untreated natural fiber long pants	Х		1	-	-
Arc-rated long-sleeve shirt		Х	Х	Х	Х
Arc-rated pants		Х	Х	Х	Х
Arc-rated coverall		X	X	X	X
Arc-rated arc flash suit jacket		Х	Х	Х	Х
Arc-rated arc flash suit pants		Х	Х	Х	Х
Arc-rated arc flash suit hood		Х	Х	Х	X
Arc-rated jacket, parka or rainwear		AN	AN	AN	AN
Hard hat		Х	Х	Х	Х
Safety glasses or goggles	Х	Х	Х	Х	Х
Hearing protection	Х	Х	Х	Х	Х
Leather gloves	AN	X	X	X	X
Leather work shoes		Х	Х	Х	X

NOTES: 70E 130.7(C)(16) / Z462 Table 5

Arc rating for garments is expressed in calories per centimeter squared (cal/cm²)
 When rubber insulating gloves (IG) with leather protectors are required by NFPA 70E130.7(C)(15)(a) /

- CSA Z462 Table 4A, additional leather gloves or arc-rated gloves shall not be required. An alternate to arc rated shirts and pants in HRC 1 or HRC 2 is an arc rated coveralls with minimum of
- 4 cal/cm2 for HRC 1 and minimum of 8 cal/cm2 for HRC 2
- **E** Face shields are required for HRC 1 (4 cal/cm²) and HRC 2 (8 cal/cm²) requires the use of balaclava/sock and wrap-around guarding to protect face, forehead, ears and neck with a minimum of 8 cal/cm2 Alternatively an appropriately arc-rated flash suit hood may be used.
- # Minimum arc rating of 25 is required for HRC 3 which can be accomplished using a total FR
- clothing system [shirt and pants and/or coveralls and/or coat and pant] and hood.
- ¤ Minimum arc rating of 40 is required for HRC 4 which can be accomplished using a total FR clothing system [shirt and pants and/or coveralls and/or coat and pant] and hood



able D 600 V Class Motor Control Centers (MCCs) lote 2 (except as indicated)		
Perform infrared thermography and other non-contact inspections outside	LWG	1
the restricted approach boundary		1
CB or fused switch or starter operation with enclosure doors closed	LWG	0
Reading a panel meter while operating a meter switch	LWG	0
CB or fused switch or starter operation with enclosure doors open	LWG	1
Work on energized electrical conductors and circuit parts, including voltage testing	IG/IT	2
Work on control circuits with energized electrical conductors and circuit parts 120 V or below, exposed	IG/IT	0
Work on control circuits with energized electrical conductors and circuit parts 120 V or above, exposed	IG/IT	2
Insertion or removal of individual starter "buckets" from MCC- Note 3	IG	4
	10	2
Application of safety grounds, after voltage test Removal of bolted covers — Note 3	IG	
(to expose bare, energized electrical conductors and circuit parts)	LWG	4
Opening hinged covers — <i>Note 3</i> (to expose bare, energized electrical conductors and circuit parts)	LWG	1
Work on energized electrical conductors and circuit parts of utilization equipment fed directly by a branch circuit of the motor control center	IG/IT	2
able E 600 V Class Switchgear		
(with power circuit breakers or fused switches) Note 4 Perform infrared thermography and other non-contact inspections outside	· · ·	
the restricted approach boundary	LWG	2
CB or fused switch operation with enclosure doors closed	LWG	0
Reading a panel meter while operating a meter switch	LWG	0
CB or fused switch operation with enclosure doors open	LWG	1
Work on energized electrical conductors and circuit parts, including voltage testing	IG/IT	2
Work on control circuits with energized electrical conductors and circuit parts 120 V or below, exposed	IG/IT	0
Work on control circuits with energized electrical conductors and circuit parts 120 V or above, exposed	IG/IT	2
Insertion or removal (racking) of CBs from cubicles, doors open or closed	LWG	4
Application of safety grounds, after voltage test	IG	2
Removal of bolted covers (to expose bare, energized electrical conductors and circuit parts)	LWG	4
Opening hinged covers (to expose bare, energized electrical conductors and circuit parts)	LWG	2
able X*		
azard Risk Catedories that are known to be Extremely Danderd		4-
480V Building Service Entrance Equipment	IG/IT	4
lazard Risk Categories that are Known to be Extremely Dangerd 480V Building Service Entrance Equipment Equipment on 480V/secondary side of an Ind/Comm substation All equipment on the load side of circuit breakers containing a short-time delay setting. Temporary removal of short time-delay is recommended.	IG/IT IG/IT	4-

General Notes : (applicable to the tasks that are 600 volts or less)

- Insulating rubber gloves are gloves rated for the maximum line-to-lin which work will be done.
- (b) Insulated tools rated and tested for the maximum line-to-line voltage upon which work will be done, and are manufactured and tested in accordance with ASTM F1505 & CAN/ULC-D60900, Standard Specification for Insulated and Insulating Hand Tools: 1000VAC / 1500VDC
- (c) For systems rated less than 1000 volts, the fault currents and upstream protective device clearing times are based on an 18 in. working distance.
- (d) For equipment protected by upstream current limiting fuses with arcing fault current in their current limiting range (1/2 cycle fault clearing time or less), the hazard/risk category required may be reduced by one number.)

Specific Notes: (as referenced within the tables)

- Max: of 25 kA short circuit current available; max. of 0.03 sec (2 cycle) fault clearing time: min. 18" workin Potential arc flash boundary with exposed energized conductors or circuit parts using above parameters: 19" 2. Max. of 65 kA short circuit current available; max. of 0.03 sec (2 cycle) fault clearing time: min. 18" working Potential arc flash boundary with exposed energized conductors or circuit parts using above parameters: 53"
- 3. Max. of 42 kA short circuit current available; max. of 0.33 sec (20 cycle) fault clearing time: min. 18" working
- Potential arc flash boundary with exposed energized conductors or circuit parts using above parameters: 165" 4. Max. of 35 kA short circuit current available; max. of up to 0.5 sec (30 cycle) fault clearing time; min. 18" working
- Potential arc flash boundary with exposed energized conductors or circuit parts using above parameters: 233"

- complete ARC FLASH HAZARD ANALYSIS should be done, if fault clearing times vary described within the Specfic Notes, rendering these tables alone INSUFFICIENT.
- 2. IG/IT indicates the required use of insulating rubber gloves, leather protectors & insulated tools.
- 3. IG indicates a requirement for the use of insulating rubber gloves and leather protectors
- 4. LWG indicates a requirement of leather gloves.
- 5. Hazard Risk Category (HRC) is defined in the last column, by one of five categories 0, 1, 2, 3 & 4 (0 being the least dangerous and 4 being the most dangerous)

650 Jacksonville Road | Burlington, NJ 08016 | 609.387.1040 | 800.654.1292 | fax 609.386.8885 | tools@cementexusa.com | www.cementexusa.com

1000 VAC

ISMUC Tested to 10,000 VAC and Rated for 1,000 VAC when working on or around live parts

Insulated Hand Tools - Where and When

"OSHA - Electrical, Safeguards for personal protection 1910.335(a)(2)(i)

When working near exposed energized conductors or circuit parts, each employee shall use insulated tools or handling equipment if the tools or handling equipment might make contact with such conductors or parts..."

"2012 Edition NFPA 70E® STANDARD for Electrical Safety in the Workplace® 130.7(D)(1) Insulated Tools and Equipment.

Employees shall use insulated tools or handling equipment, or both, when working inside the *limited approach boundary* of exposed energized electrical conductors or circuit parts where tools or handling equipment might make accidental contact..."

"def. Boundary, Limited Approach

An approach limit at a distance from an exposed energized electrical conductor or circuit part within which a shock hazard exists."

ex. *Limited Approach Boundary Exposed Fixed conductors 50V - 750V AC = <u>3ft 6in</u> 100V - 1kV DC = <u>3ft 6in</u>

Cementex has the tools available to help you comply with the stringent standards established by OSHA, NFPA, and CSA. Knowledge, experience, and commitment to quality make Cementex the trusted source for safety tools and equipment.

*2012 NFPA 70E® Tables 130.4 (C)(a), 130.4(C)(b)

Tools comply with ASTM F1505 and IEC 900 standards and help meet the requirements of OSHA 1910.331-335, NFPA 70E®, and CSA-Z462.

ITS-30MTK

IR38-LC: 3/8" Square Drive Ratchet Extension Bars: 3", 6" 12-Point SAE Deep Wall Sockets: 3/8", 7/16", 1/2", 9/16", 5/8", 11/16", 3/4", 13/16" Pliers: 9" Linesman's, 7" Diagonal Cut, 7" Chain Nose SAE Box End Wrenches: 3/8", 7/16", 1/2", 9/16", 5/8", 11/16", 3/4", 13/16" Screwdrivers: 1/8" X 5", 3/16" X 4-1/2", 1/4" X 6" Cabinet Tip, #1 X 3", #2 X 4" Phillips Tip Orange Flashlight 20" Tool Box ITS-MB430

ITS-30MTK plus 30200TW38I 3/8" Square Drive Torque Wrench 30-200 Inch Pounds In a Blow Molded Carrying Case

ITS-MB430M

ITS-30MTK with 1/2" Square Drive Torque Wrench, Metric Sockets and Box End Wrenches
150750TW121: 1/2" Square Drive Torque Wrench 150-750 Inch Pounds
IR12-LC: 1/2" Square Drive Ratchet
Extension Bars: 2", 5"
12-Point Metric Deep Wall Sockets: 9mm, 10mm, 12mm, 14mm, 15mm, 19mm, 21mm, 22mm
Metric Box End Wrenches: 10mm, 11mm, 12mm, 14mm, 15mm, 16mm, 18mm, 20mm

> ITS-MB431 30200TW38I: 3/8" Square Drive Torque Wrench 30-200 Inch Pounds IR38-LC: 3/8" Square Drive Ratchet Extension Bars: 3", 6" 12-Point SAE Deep Wall Sockets: 3/8", 7/16", 1/2", 9/16", 5/8", 11/16", 3/4", 13/16" Pliers: 9" Linesman's, 7" Diagonal, 7" Chain Nose SAE Wratcheting Box End Wrenches: 3/8", 7/16", 1/2", 9/16", 5/8", 11/16", 3/4", 13/16" Screwdrivers: 1/8" X 5", 3/16" X 4-1/2" 1/4" X 6" Cabinet Tip. #1 X 3", #2 X 4" Phillips Tip **Orange Flashlight Blow Molded Carrying Case**



ITS-MB431

ITS-MB431M

ITS-MB431 replacing SAE with Metric Sockets and Ratcheting Box End Wrenches 12-Point Metric Deep Wall Sockets: 10mm, 12mm, 13mm, 14mm, 15mm, 17mm, 19mm, 20mm Metric Wratcheting Box End Wrenches: 10mm, 12mm, 13mm, 14mm, 15mm, 17mm, 19mm, 20mm