




Revisions



Type No.

| VA | CATALOG NUMBER | VOLTAGE | | WIRING DIAGRAM | WEIGHT | PHASE | FREQ. |
|----|-----------------|---------|-------|----------------|--------|----------|-------|
| | | HIGH | LOW | | | | |
| 50 | TA-83300 | 600 | 12/24 | | 4 Lbs | 1 ϕ | 60 Hz |

TYPICAL PERFORMANCE DATA

| | |
|---------------|-------|
| Winding Rise: | 80°C |
| Insulation: | 130°C |
| Windings: | CU |

| | | | |
|------------|--------|-----------|--|
| Standards: | UL/CSA | Markings: | |
|------------|--------|-----------|--|

Industrial Control Transformer

| | |
|--------------------|--|
| Typical Efficiency | |
| Full Load Losses | |
| No Load Losses | |

| A | B | C | D | E | F |
|------|------|------|------|------|-----------|
| 4.13 | 3.00 | 2.59 | 2.50 | 2.30 | .22 x .50 |

A PRINTS TO **CONTROL 7**